


Pressure Test Gauge

Weldtec® introduces a simple to use water pressure test gauge to check your TIG, MIG or PLASMA water pump out-put pressure.

Most TIG, MIG and PLASMA torches are designed to operate at approximately 50 PSI water in-let pressure. Too low a pressure may result in over heating, too high a pressure may result in ballooning and bursting of the water lines or power cable. This simple to use test gauge has a convenient hand nut and industry standard connections.



ORDERING INFORMATION

PART NUMBER	DESCRIPTION
C100TG	Pressure Test Gauge



WeldTec® - "where quality and innovation never ends"

Specifications subject to change without notice.